

PROJECT	STREAM NAME	STREAM SIGNIFICANCE	STREAM QUALITY		LENGTH OF ADDED IN-STREAM BREAKS (m)	LENGTH OF ADDED CROSSINGS (m)	CORRIDOR WIDTH TARGET ACHIEVED
			PRE-DEVELOPMENT CONDITION	REHABILITATION OBJECTIVES			
Oran Park	South Creek	Category 1	Vegetation within the South Creek corridor is floristically and structurally diverse. However there were only stagnant pools of water at the time of surveys. Sections of South Creek were found to be of moderate aquatic habitat quality, due to the presence of mostly native riparian vegetation, reasonable bank stability and the occurrence of flow (Ecological 2007)	Revegetation will be undertaken to enhance the habitat potential of the riparian corridor.	0	20	Yes (40m and 10 m buffer)
Oran Park	Unnamed	Category 3	Heavily disturbed drainage line within a grazed landscape. Some canopy trees present.	Revegetation to provide water quality and bank stability.	0	10	Yes (10 m from top of bank)